

ComAnt CAS3 Application Installation

THE MAST SHOULD OVERLOOK THE DIPOLE END

For proper weather protection all connectors and cable junctions should be covered by self-amalgamating tape or equivalent

Splitter harness shall be tied to the mast after the installation

2 Pcs CS

Direction of maximum radiation

$$S \text{ [m]} = 300 / f \text{ [MHz]}$$

3 Pcs CAY

